

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 24 JUNE 2005

AUSTRALIA – VICTORIA

No. 55 - 2005

PORT PHILLIP

MELBOURNE
VICTORIA HARBOUR, CENTRAL PIER

Date: From approximately 27 June

Details: Mariners are advised of the decommissioning of the following beacons on Central Pier, Victoria Harbour at approximate locations

No 61: F G 37°49.040'S, 144°56.435' E (WGS 84)

No 62: F R 37°49.073'S, 144°56.458' E (WGS 84)

Buoys will replace the beacons at the following approximate locations and with the corresponding lit characteristics;

No 61: FI G 37°49.035'S, 144°56.424' E (WGS 84)

No 62: FI R 37°49.078'S, 144°56.453' E (WGS 84)

Charts Affected: AUS 154

Further Notice: No Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 JULY 2005

AUSTRALIA - VICTORIA

No. 57 - 2005

PORT PHILLIP

MOUNT MARTHA AQUACULTURE FISHERIES RESERVE
SPECIAL MARK BUOYS ESTABLISHED

Date: On or about 13 July 2005.

Details: Mariners are advised of the installation of new boundary mark buoys for the Mount Martha Aquaculture Fisheries Reserve. The 150 ha aquaculture fisheries reserve will be marked with buoys at the NW, NE, SE & SW corners. Boating access within the reserve area will be of limited access as specified by the Draft Eastern Port Phillip Bay Aquaculture Fisheries Reserves Management Plan.

The corner boundaries will be identified with **Special Mark buoys** with synchronised light characteristic **Fl Y (4) 10s** at approximate locations as follows:

| Boundary | Latitude South WGS 84 | Longitude East WGS 84 |
|-------------------|----------------------------------|----------------------------------|
| North West | 38° 13.909' | 144° 59.917' |
| North East | 38° 13.928' | 145° 01.059' |
| South West | 38° 14.395' | 144° 59.903' |
| South East | 38° 14.415' | 145° 01.046' |

The buoys will exhibit a **yellow X** top mark with "**AQUACULTURE**" text.

Mariners are advised to navigate with caution during the installation of the buoys.

Charts & publications affected: AUS 143, 158

Further Notice: No further notices will be issued.

If you require any further information please contact Parks Victoria on 13 19 63, or Fisheries Victoria on 136 186 regarding the Management Plan.

**STUART ORD
REGIONAL MANAGER
CITY & BAYS**

This Notice to Mariners is issued by Parks Victoria on behalf of Department of Primary Industries.

Parks Victoria is not responsible for the accuracy of the information contained herein.

***Healthy Parks
Healthy People***

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 JULY 2005

AUSTRALIA - VICTORIA

No. 58 - 2005

PORT PHILLIP, CORIO BAY

PT LILLIAS

BATES POINT AQUACULTURE FISHERIES RESERVE
SPECIAL MARK BUOYS ESTABLISHED

Date: On or about 13 June 2005.

Details: Mariners are advised of new boundary mark buoys for the Bates Point Aquaculture Fisheries Reserve. The 25 ha aquaculture fisheries reserve will be marked at the NW, NE, SE and SW corners. Boating access within the reserve area will be of limited access as specified by the Draft Geelong Arm Phillip Bay Aquaculture Fisheries Reserves Management Plan.

The corner boundaries will be identified with **Special Mark buoys** with synchronised light characteristic **FI Y (4) 12s** at approximate locations as follows:

| Boundary | Latitude South WGS 84 | Longitude East WGS 84 |
|-------------------|----------------------------------|----------------------------------|
| North West | 38° 05.451' | 144° 27.304' |
| North East | 38° 05.459' | 144° 27.646' |
| South West | 38° 05.722' | 144° 27.295' |
| South East | 38° 05.729' | 144° 27.637' |

The buoys will exhibit a **yellow X** top mark with "**AQUACULTURE**" text.

Mariners are advised to navigate with caution during the installation of the buoys.

Charts & publications affected: AUS 143, 157

Further Notice: No further notices will be issued.

If you require any further information please contact Parks Victoria on 13 19 63, or Fisheries Victoria on 136 186 regarding the Management Plan.

**STUART ORD
REGIONAL MANAGER
CITY & BAYS**

This Notice to mariners is issued by Parks Victoria on behalf of Fisheries Victoria.
Parks Victoria is not responsible for the accuracy of the information contained herein.

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 3 AUGUST 2005

AUSTRALIA – VICTORIA

No. 70 - 2005

PORT PHILLIP

ST KILDA ISOLATED DANGER BUOY REINSTATED

Date: Immediate

Details: Mariners are advised that the St Kilda isolated danger buoy with characteristics Fl (2) 10s at the approximate position 37°52.212' S 144°57.552' E (WGS 84) has been reinstated.

Charts Affected: AUS 143, 155

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 22 AUGUST 2005

AUSTRALIA – VICTORIA

No. 73 - 2005

PORT PHILLIP

CORIO BAY, LIMEBURNERS PT

Limeburners Pt Boat harbour - Island breakwater

Date: Immediate

Previous Notice: 91 (T) 2004 refers and is cancelled

Details: Mariners are advised of the completion of an island breakwater located approximately 60 metres offshore from the entrance to the boat harbour. The breakwater is approximately 70 metres in length.

The NE and SW extents of the breakwater are lit at the following approximate positions.

F R 38°08.544' S 144 ° 23.093' E

F G 38°08.528' S 144 ° 23.124' E

Charts Affected: AUS 143, 157

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

***Healthy Parks
Healthy People***

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 22 AUGUST 2005

AUSTRALIA – VICTORIA

No. 74T- 2005

PORT PHILLIP

HOBSONS BAY

COMPLETION OF DREDGING AND CONTINUATION OF MARINA WORKS, PARSONS MARINA

Date: Immediate until 30 September 2005

Previous Notice: 38(T)/05 refers and is cancelled

Details: Mariners are advised of the completion of dredging and continuation of marina redevelopment works at Parsons Marina, Williamstown, located at approximate position 37°51.23'S, 144°54.11'E (WGS84).

The installation of a 170m concrete floating pontoon main jetty with four finger arm pontoon jetties attached (ranging from 60 to 76m in length) is nearing completion.

5 No. unmarked piles have been installed marking the approach channel to Parsons Marina and may pose a hazard to navigation.

All works will be carried out during daylight hours and all hazards to boating including floating plant and equipment will be marked with yellow flashing lights. Short delays may be experienced due to plant movement in the vicinity of the works area.

Mariners are advised to exercise extreme caution when navigating in the area of the 5 No. unmarked piles, floating plant and equipment.

For general communication, please contact Parsons Marina on (03) 9397-7799.

Charts Affected: AUS 143,154,155

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 22 August 2005

AUSTRALIA – VICTORIA

No. 75 - 2005

PORT PHILLIP

HOBSONS BAY

COMPLETION OF MARINA WORKS AT SAVAGE MARINA, WILLIAMSTOWN

Date: Immediate

Previous Notice: 122(T)/04 and 14(T)/05 refers and is cancelled

Details: Mariners are advised of the completion of marina redevelopment works at Savage Marina, Williamstown, located at approximate position 37°51.64'S, 144°54.29'E (WGS84).

For general communication, please contact Savage Marina on (03) 9397-6513.

Charts Affected: AUS 143,154,155

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 7 OCTOBER 2005

AUSTRALIA – VICTORIA

No. 92 - 2005

PORT PHILLIP

CORIO BAY

Removal of Hazardous Structures

Date: Immediate

Details: Mariners are advised of the removal of two hazardous dolphins at approximate Charted positions (WGS 84);

| | |
|-----------------------|------------------------------|
| Starboard 'Steamboat' | 38°06.697' S 144 ° 30.983' E |
| South Cardinal | 38°08.518' S 144 ° 29.759' E |

Charts Affected: AUS 157

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

***Healthy Parks
Healthy People***

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 30 SEPTEMBER 2005

AUSTRALIA – VICTORIA

No. 87T - 2005

WESTERN PORT

EVANS INLET

CONSTRUCTION OF TOORADIN BOARDWALK

Date: Immediate until 1 February 2006

Details: Mariners are advised of the works associated with the construction of the Tooradin Boardwalk at Evans Inlet, Tooradin located at approximate position 38°12.780' S 145°22.741' E (WGS84).

The works will include the construction of a 140 metre length timber boardwalk alongside the existing road bridge. A barge mounted pile driving rig will be anchored at the site for approximately 3 months during construction.

All works will be carried out during daylight hours and all hazards to boating including floating plant and equipment will be marked appropriately.

Mariners are advised to exercise caution when navigating in the area of the floating plant and equipment.

For general communication, please contact:

- William Fox (Project Manager, W. Fox Engineering P/L) on (03) 5967-1885; or
- Casey City Council on (03) 9705-5200.

Charts Affected: AUS 150, 151

Further Notice: A further Notice will be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 25 OCTOBER 2005

AUSTRALIA – VICTORIA

No. 94 T - 2005

PORT PHILLIP

Patterson River Entrance Sand Bypass Trial

Date: On or about 27th October – 10th November

Details: Mariners are advised of the trial of a sand bypass system at the entrance to Patterson River, Carrum.

The buried bypass unit will be submerged at a depth of approximately -5.0 metres Chart Datum.

The unit will be mobilised on site by workboat 'Dangerfield' which can be contacted on 0413 007 387 during the installation.

Disruption to channel access is anticipated during the mobilisation and Mariners are requested to proceed with caution in the vicinity of the floating plant.

Mariners navigating the channel are reminded to observe the daymarks relating to vessels restricted in ability to manoeuvre and to pass on the side indicated by two black diamonds.

Charts Affected: AUS 143

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 7 NOVEMBER 2005

AUSTRALIA – VICTORIA

No. 97 - 2005

PORT PHILLIP, CORIO BAY

Grassy Point, Aquaculture Special Mark Pile destroyed

Date: Immediate

Details: Mariners are advised that the NE corner pile indicating the boundary of Grassy Point Aquaculture Fisheries Reserve has been destroyed at approx. location 388 06.188' 1448 42.186'.

A special mark buoy displaying a yellow 'X' and lit characteristic FI (3) Y 5s has been established in position.

Mariners are advised to navigate with caution in the vicinity.

Charts Affected: AUS 157, 143

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 17 NOVEMBER 2005

AUSTRALIA – VICTORIA

No. 98 T- 2005

PORT PHILLIP

**Mount Martha Aquaculture Fisheries Reserve,
Aquaculture Special Mark Buoy Partially Submerged**

Date: Immediate

Details: Mariners are advised that the NE corner buoy indicating the boundary of the Mount Martha Aquaculture Fisheries Reserve is partially submerged and has no functioning light.

The buoy is at approximate location 38° 13.928' 145° 01.059' (WGS84).

Mariners are advised to navigate with caution in the vicinity.

Charts Affected: AUS 158, 143

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 24 NOVEMBER 2005

AUSTRALIA – VICTORIA

No. 100 T - 2005

PORT PHILLIP

Patterson River Entrance Sand Bypass Trial
Buoy marking obstruction in Channel

Date: Immediate

Details: Mariners are advised that the sand bypass unit has been buried at the entrance to Patterson River, Carrum.

The buried bypass unit is buried to a depth of approximately -5.0 metres Chart Datum.

A red pimple buoy at approximate position 38804.404' S 145807.177' E marks a section of the flexible pipeline at approximately -2.0 metres Chart Datum.

The pipeline will be adjusted to increase the clearance depth early next week, weather conditions permitting.

Mariners are advised to navigate with caution in the vicinity.

Vessels with a draught greater than the obstruction are advised to avoid the immediate area marked by the buoy.

Charts Affected: AUS 143

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 5 DECEMBER 2005

AUSTRALIA – VICTORIA

No. 104 T- 2005

PORT PHILLIP

P3 Mark – Unlit

Date: Immediate

Details: Mariners are advised that the P3 mark located at approximate position 37°53.386'S 144°52.825'E (WGS 84) light is currently unlit.

Mariners are advised to navigate with caution in the vicinity of the mark.

Charts Affected: AUS 155

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 5 DECEMBER 2005

AUSTRALIA – VICTORIA

No. 105 T- 2005

PORT PHILLIP

Patterson River Entrance Sand Bypass Trial

Date: Immediate

Previous Notice: 94 T & 101T are referred and cancelled

Details: Mariners are advised that the 6 month trial of a sand bypass system has commenced at Patterson River, Carrum.

The sand bypass unit is buried at the River entrance central to the north and south training walls to a depth of approximately -5.0 metres Chart Datum.

All hazards to navigation have been removed.

Mariners are advised to check updated depth information on www.parkweb.vic.gov.au.

Charts Affected: AUS 143

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICES TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 JANUARY 2005

AUSTRALIA - VICTORIA

No. 01(T)/05

VICTORIAN NOTICES TO MARINERS

NOTICES IN FORCE

Date: On the 1st January 2005

Former Notice: 01(T)/04 refers and is hereby cancelled.

Details: The following Victorian Notices to Mariners are in force.
Notices can be downloaded from the Port of Melbourne Corporation website at: www.portofmelbourne.com

| No. | Region | Location | Details |
|-------------|---------------|--------------------------|-------------------------------------------|
| 61 (T) / 00 | Western Port | Hastings | Reduced depth in channel |
| 55 (T) / 01 | Portland | Portland Harbour | Reduced depths at berths |
| 37 / 02 | Port Phillip | Ports of Melb. / Geel. | Amendments to Harbour Master's Directions |
| 58 (T) / 02 | Port Phillip | Pinnacle Channel | Scientific research buoy |
| 68 / 02 | Port Phillip | Port of Melbourne | Amendments to Harbour Masters Directions |
| 72 / 02 | Port Phillip | Port of Melbourne | Amendments to Harbour Masters Directions |
| 01 (T) / 03 | Port Phillip | Entrance to Port Phillip | Wave riders established |
| 08 (T) / 03 | Port Phillip | Entrance to Port Phillip | Wave buoys established |
| 11 / 03 | Port Phillip | Entrance to Port Phillip | Spherical buoy removed |
| 36 / 03 | Port Phillip | Ports of Melb. / Geel. | Amendments to Harbour Masters Directions |
| 41 (T) / 03 | Western Port | Port of Hastings | Fairway racon unreliable |
| 51 / 03 | Port Phillip | Ports of Melb. / Geel. | Management of port waters / HM Directions |
| 62 / 03 | Port Phillip | Port of Melbourne | Amendments to Harbour Masters Directions |

| No. | Region | Location | Details |
|-----------|--------------|----------------------------|--------------------------------------------|
| 02/04 | Port Phillip | Port of Melbourne | Amendments to Harbour Masters Directions |
| 05(T)/04 | Port Phillip | Sorrento | Sorrento Channel buoy |
| 36/04 | Port Phillip | Port of Geelong | Management of port waters / HM Directions |
| 54(T)/04 | Port Phillip | Port of Geelong | Declared berth depths |
| 62/04 | Port Phillip | Port of Geelong | Port Security - Port of Geelong |
| 62/Err | Port Phillip | Port of Geelong | Erratum to Port Security Geelong |
| 63(T)/04 | Westernport | Eastern entrance | Western Port / Eastern Entrance buoy |
| 64(T)/04 | Port Phillip | Port of Melbourne | Port Security - Port of Melbourne |
| 66/04 | Westernport | Port of Hastings | Port Security - Port of Hastings |
| 70/04 | Apollo Bay | Apollo Bay Harbour | Harbour entrance - depth reduction |
| 72(T)/04 | Gippsland | Corner Inlet & Port Albert | No.17 beacon destroyed |
| 73(T)/04 | Port Phillip | Port of Melbourne | Declared berth depths |
| 75(T)/04 | Port Phillip | South Channel | Shoaling - Nicholson Knoll |
| 76/04 | Port Phillip | West Channel | West Channel closure – HM Directions |
| 80(T)/04 | Port Phillip | Port Phillip | Deep draught transit procedures |
| 83/04 | Port Phillip | Port Phillip | Notice to vessels navigating off the Heads |
| 91(T)/04 | Port Phillip | Corio Bay | Limeburners Pt. Boat Harbour |
| 96(T)/04 | Port Phillip | Dromana Bay | Construction of rock walls |
| 107(T)/04 | Gippsland | Corner Inlet & Port Albert | Barry Beach channel – reduced depth |
| 108(T)/04 | Port Phillip | Port of Melbourne | Westgate Bridge - maintenance works |
| 113/04 | Port Phillip | Port of Melbourne | Fawkner beacon – transit zone established |
| 114/04 | Port Phillip | Port of Melbourne | Channel beacons upgrade |
| 115/04 | Gippsland | Corner Inlet & Port Albert | Port Albert channel No.2 buoy redeployed |
| 116(T)/04 | Port Phillip | Hobsons Bay | Dredging, Parsons Marina |
| 117/04 | Gippsland | Port of Gippsland Lakes | North Arm channel lights |
| 120(T)/04 | Port Phillip | Blairgowrie | Blairgowrie boat harbour maintenance |
| 121(T)/04 | Port Phillip | Port Phillip | Rock groyne works, Sandridge |
| 122(T)/04 | Port Phillip | Hobsons Bay | Construction of Savage Marina |
| 123/04 | Port Phillip | Mordialloc Creek | Dredging & buffer piles complete |

Victorian Notices to Mariners are issued by a number of different Authorities. This notice has been collated from the latest information held by the Port of Melbourne Corporation.

Information relating to the above notices are available at the Port of Melbourne Corporation website. Specific queries relating to Notices should be directed to the issuing authority.

Further Notice: Further Notice will be issued.

T. M. MUIR
HARBOUR MASTER

**Victorian Notices to Mariners can be downloaded from the
Port of Melbourne Corporation website
www.portofmelbourne.com**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 15T - 2005

WESTERN PORT

SHOREHAM

SPECIAL MARK MISSING

STORM DAMAGE

Date: Immediate

Details: Mariners are advised that the Special Mark at the southern boundary of the Shoreham No Personal Watercraft zone located at approximate position 38826.430' S 14582.974' E (WGS 84) has been destroyed.

Mariners are advised to exercise caution when navigating in the area and note the shore marks indicating the restriction zone.

Charts Affected: AUS 150

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 15T - 2005

WESTERN PORT

SHOREHAM

SPECIAL MARK MISSING

STORM DAMAGE

Date: Immediate

Details: Mariners are advised that the Special Mark at the southern boundary of the Shoreham No Personal Watercraft zone located at approximate position 38826.430' S 14582.974' E (WGS 84) has been destroyed.

Mariners are advised to exercise caution when navigating in the area and note the shore marks indicating the restriction zone.

Charts Affected: AUS 150

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 10 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 20T - 2005

WESTERN PORT

WATSONS INLET NO.1 STARBOARD HAND MARK MISSING

STORM DAMAGE

Date: Immediate

Details: Mariners are advised that the Watsons Inlet No.1 starboard hand mark at approximate position 38°15.651' S 145°15.758' E (WGS 84) has been destroyed.

Mariners are advised to exercise caution when navigating in the area.

Charts Affected: AUS 150, 151

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 18 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 24 - 2005

PORT PHILLIP

PORT PHILLIP HEADS MARINE NATIONAL PARK

MUD ISLANDS
INSTALLATION OF INTERMEDIATE BOUNDARY MARKS

Date: Immediate

Details: Mariners are advised of the installation of four unlit Special Mark piles to supplement the existing corner boundary marks of the Port Phillip Heads Marine National Park at Mud Islands.

Special Mark piles are located at the following intermediate boundary positions (WGS 84);
Northern boundary 144°46.03' E 38°15.60' S
Western boundary 144°45.18' E 38°16.27' S
Eastern boundary 144°46.90' E 38°16.32' S
Southern boundary 144°46.03' E 38°16.95' S

Charts Affected: AUS 143, 158, 144

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

***Healthy Parks
Healthy People***

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 23 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 27T- 2005

PORT PHILLIP

HOBSONS BAY

PARSONS MARINA DREDGING OF APPROACH CHANNEL CONTINUES, WILLIAMSTOWN

Date: From 28 February 2005 to 28 March 2005

Previous Notice: 116(T)/04 refers and is cancelled

Details: Mariners are advised of the continuation of dredging at Parsons Marina, Williamstown.

Dredging works will be carried out between approximate positions 37°51.23'S, 144°54.17'E (WGS84) and 37°51.11'S, 144°54.42'E (WGS84) utilising a clamshell dredge, with spoil disposal to a moored hopper barge. Temporary mooring piles will be progressively positioned and retrieved as work progresses. The barge will be towed to Port Phillip spoil ground to dispose material which is marked by a lit buoy with characteristics Fl(4)Y 10s at approximate position 38°00.70'S, 144°53.16E (WGS84).

All works will be carried out during daylight hours and all hazards to boating including floating plant, equipment and temporary mooring piles will be marked with yellow flashing lights.

For general communication, please contact Parsons Marina on (03) 9397-7799.

Mariners are advised to exercise caution when navigating in the area of the floating plant and equipment.

Charts Affected: AUS 143,154,155

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 21 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 26T - 2005

PORT PHILLIP

HALF MOON BAY

Date: 24 February – 7 March 2005

Details: Mariners are advised that works to the wreck **HMVS Cerberus** located at approximate position 37°58.052' S 144°48.453' E (WGS 84) are to be carried out. The works include the removal of four guns from the deck of the vessel and placement on the seabed approximately 30 metres from the vessel in approximately 4m of water.

The guns are to be removed with crane mounted on a jack up barge and additional floating plant on site. Work boat 'Taurus' can be contacted on 0408 598 947.

Mariners are advised to exercise caution and navigate at a slow speed in the vicinity of floating plant and equipment.

Charts Affected: AUS 143, 155

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 24 FEBRUARY 2005

AUSTRALIA – VICTORIA

No. 29 - 2005

PORT PHILLIP

R2 BUOY

Date: Immediate

Previous Notice: 22T refers and is cancelled

Details: Mariners are advised that the R2 buoy is located at the approximate charted position 37°58.813' S 144°58.371'E (WGS 84).

Charts Affected: AUS 143, 155

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 18 MARCH 2005

AUSTRALIA – VICTORIA

No. 33T - 2005

PORT PHILLIP

MORDIALLOC CREEK ENTRANCE SHOALING

Date: Immediate

Mariners are advised of shoaling at the entrance to Mordialloc Creek, located at approximately 38° 0.65' S, 145° 5.07 E (WGS 84).

Depth at the entrance is reported to be between 1.0 to 1.5 metres Chart Datum.

Charts Affected: AUS 143, 155

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 30 MARCH 2005

AUSTRALIA – VICTORIA

No. 37T - 2005

PORT PHILLIP

BLAIRGOWRIE

BLAIRGOWRIE BOAT HARBOUR MAINTENANCE CONTINUATION

Date: Immediate to 16 May 2005

Previous Notice: 120T/04 refers and is cancelled

Details: Mariners are advised of the continuing maintenance works associated with the Blairgowrie Boat Harbour located at approximate position 38°21.50' S 144°46.35' E (WGS 84).

Two barges will be anchored within the harbour at approximate locations;

38°21.36' S 144°46.28' E (WGS 84)

38°21.33' S 144°46.30' E (WGS 84)

The barges will be marked with yellow flashing lights from sunset to sunrise.

All works will be carried out during daylight hours and all hazards to boating including floating plant and equipment will be marked. General contact may be made on 5988 8453.

Mariners are advised to exercise caution when navigating in the area of the floating plant.

Charts Affected: AUS 143, 158

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 30 MARCH 2005

AUSTRALIA – VICTORIA

No. 38T- 2005

PORT PHILLIP

HOBSONS BAY

**PARSONS MARINA DREDGING OF APPROACH CHANNEL CONTINUES,
WILLIAMSTOWN**

Date: Immediate until 28 May 2005

Previous Notice: 27(T)/05 refers and is cancelled

Details: Mariners are advised of the continuation of dredging at Parsons Marina, Williamstown.

Dredging works will be carried out between approximate positions 37°51.23'S, 144°54.17'E (WGS84) and 37°51.11'S, 144°54.42'E (WGS84) utilising a clamshell dredge, with spoil disposal to a moored hopper barge. Temporary mooring piles will be progressively positioned and retrieved as work progresses. The barge will be towed to Port Phillip spoil ground to dispose material which is marked by a lit buoy with characteristics Fl(4)Y 10s at approximate position 38°00.70'S, 144°53.16E (WGS84).

All works will be carried out during daylight hours and all hazards to boating including floating plant, equipment and temporary mooring piles will be marked with yellow flashing lights.

For general communication, please contact Parsons Marina on (03) 9397-7799.

Mariners are advised to exercise caution when navigating in the area of the floating plant and equipment.

Charts Affected: AUS 143,154,155

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 APRIL 2005

AUSTRALIA – VICTORIA

No. 40T - 2005

PORT PHILLIP

**MAINTENANCE DREDGING COMPLETE AT
MORDIALLOC CREEK ENTRANCE**

Date: Immediate

Previous Notice: 33(T)/05 refers and is cancelled

Details: Mariners are advised that maintenance dredging has been carried out at the entrance to Mordialloc Creek, located at approximately 38° 0.65' S, 145° 5.07 E (WGS 84).

Channel depth is approximately 1.5 metres Chart Datum.

Vessel operators are advised to navigate the entrance with care as shoaling can occur due to local coastal processes.

Charts Affected: AUS 143, 155

Further Notice: No further Notice will be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 APRIL 2005

AUSTRALIA – VICTORIA

No. 41T - 2005

PORT PHILLIP

ALTONA BOAT HARBOUR ENTRANCE SHOALING

Date: Immediate

Mariners are advised of shoaling at the entrance to Altona Boat Harbour, located at approximately 37° 52.007' S, 144° 50.964 E (WGS 84).

Depth at the entrance is reported to be between less than 1.0 metre Chart Datum.

Charts Affected: AUS 143, 155

Further Notice: A further Notice to be issued

If you require any further information please contact Hobsons Bay Council on 9932 1000

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

This Notice to Mariners is issued by Parks Victoria on behalf of Hobsons Bay Council.

The Parks Victoria is not responsible for the accuracy of the information contained herein.

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 APRIL 2005

AUSTRALIA – VICTORIA

No. 42T- 2005

WESTERN PORT

NEWHAVEN

**DREDGING OF NEWHAVEN MARINA
& ENTRANCE CHANNEL**

Date: 4 April – 13 May 2005

Details: Mariners are advised of dredging at Newhaven Marina and entrance channel, Newhaven, located at approximate position 38°30.746'S, 145°21.779'E (WGS84).

Dredging works will be carried out by cutter suction dredge with disposal via pipeline to bunded area onshore.

All works will be carried out during daylight hours and all hazards to boating including floating plant and equipment will be marked with yellow flashing lights.

For general communication, please contact Newhaven Yacht Squadron on (03) 5956 7515.

Mariners are advised to exercise caution when navigating in the area of the floating plant and equipment.

Charts Affected: AUS 150

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 6 MAY 2005

AUSTRALIA – VICTORIA

No. 45 - 2005

PORT PHILLIP

HOBSONS BAY, WILLIAMSTOWN
COMMONWEALTH RESERVE

Date: Immediate

Details: Mariners are advised of localised shoaling in the vicinity of the Commonwealth Reserve, Williamstown.

An unlit isolated danger buoy has been installed at approximate location 37° 51.689' S, 144° 54.286' E (WGS 84).

Charts Affected: AUS 143, 155, 154

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 13 MAY 2005

AUSTRALIA – VICTORIA

No. 47 - 2005

PORT PHILLIP

FRANKSTON PIER

Date: Immediate

Details: Mariners are advised that the Frankston Pier light located at approximate position 38°8.733' S 145°6.673'E (WGS 84) has been upgraded to characteristic Fl.G 4s 4M.

Charts Affected: AUS 143

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 31 MAY 2005

AUSTRALIA – VICTORIA

No. 53 - 2005

WESTERN PORT

NEWHAVEN

**DREDGING OF NEWHAVEN MARINA
& ENTRANCE CHANNEL**

Date: Immediate

Details: Mariners are advised of the completion of maintenance dredging at Newhaven Marina and entrance channel, Newhaven, located at approximate position 38°30.746'S, 145°21.779'E (WGS84).

For general communication, please contact Newhaven Yacht Squadron on (03) 5956 7515.

Charts Affected: AUS 150

Further Notice: No further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 2 JUNE 2005

AUSTRALIA – VICTORIA

No. 54T - 2005

PORT PHILLIP

DROMANA BAY, SAFETY BEACH

MARTHA COVE

Date: Immediate – 30 October 2005

Previous Notice: 8(T)/05 refers and is cancelled

Details: Mariners are advised of the completion of the breakwater works associated with the Martha Cove development at approximate position 38°18.46'S, 144°59.49' E (WGS 84).

Inland marina works are ongoing and no access is available for vessels.

Charts Affected: AUS 143, 158

Further Notice: A further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 4 JULY 2005

AUSTRALIA - VICTORIA

No. 58 - 2005

PORT PHILLIP, CORIO BAY

PT LILLIAS

BATES POINT AQUACULTURE FISHERIES RESERVE
SPECIAL MARK BUOYS ESTABLISHED

Date: On or about 13 June 2005.

Details: Mariners are advised of new boundary mark buoys for the Bates Point Aquaculture Fisheries Reserve. The 25 ha aquaculture fisheries reserve will be marked at the NW, NE, SE and SW corners. Boating access within the reserve area will be of limited access as specified by the Draft Geelong Arm Phillip Bay Aquaculture Fisheries Reserves Management Plan.

The corner boundaries will be identified with **Special Mark buoys** with synchronised light characteristic **FI Y (4) 12s** at approximate locations as follows:

| Boundary | Latitude South WGS 84 | Longitude East WGS 84 |
|-------------------|----------------------------------|----------------------------------|
| North West | 38° 05.451' | 144° 27.304' |
| North East | 38° 05.459' | 144° 27.646' |
| South West | 38° 05.722' | 144° 27.295' |
| South East | 38° 05.729' | 144° 27.637' |

The buoys will exhibit a **yellow X** top mark with "**AQUACULTURE**" text.

Mariners are advised to navigate with caution during the installation of the buoys.

Charts & publications affected: AUS 143, 157

Further Notice: No further notices will be issued.

If you require any further information please contact Parks Victoria on 13 19 63, or Fisheries Victoria on 136 186 regarding the Management Plan.

**STUART ORD
REGIONAL MANAGER
CITY & BAYS**

This Notice to mariners is issued by Parks Victoria on behalf of Fisheries Victoria.
Parks Victoria is not responsible for the accuracy of the information contained herein.

*Healthy Parks
Healthy People*

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 7 JULY 2005

AUSTRALIA – VICTORIA

No. 61T - 2005

PORT PHILLIP

BLAIRGOWRIE

BLAIRGOWRIE BOAT HARBOUR MAINTENANCE COMPLETION

Date: Immediate

Previous Notice: 37T/05 refers and is cancelled

Details: Mariners are advised of the completion of maintenance works associated with the Blairgowrie Boat Harbour located at approximate position 38°21.50' S 144°46.35' E (WGS 84).

Two barges utilised for the works are anchored within the harbour at approximate locations;

38°21.36' S 144°46.28' E (WGS 84)

38°21.33' S 144°46.30' E (WGS 84)

The barges are marked with yellow flashing lights from sunset to sunrise.

General contact may be made on 5988-8453.

Mariners are advised to exercise caution when navigating in the area of the floating plant.

Charts Affected: AUS 143, 158

Further Notice: A further Notice will be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 22 November 2005

AUSTRALIA – VICTORIA

No. 99 - 2005

PORT PHILLIP

HOBSONS BAY

NEW POSITION OF ROSNY ST ROCK GROUYNE STARBOARD MARK, BEACON COVE

| | |
|-------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Date: | Immediate |
| Previous Notice: | 121(T)/04 refers and is cancelled |
| Details: | <p>Mariners are advised that the new location of the starboard hand unlit navigation aid at Rosny Street rock groyne, Beacon Cove is located at approximate position 37°50.471'S, 144°55.402'E (WGS84).</p> <p>The starboard hand mark was re-positioned seaward by 60 metres to accommodate the extension of the Rosny Street rock groyne.</p> |
| Charts Affected: | AUS 143,154,155 |
| Further Notice: | No further Notice to be issued |

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

VICTORIAN NOTICE TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 2 DECEMBER 2005

AUSTRALIA – VICTORIA

No. 103 T- 2005

PORT PHILLIP

Patterson River Entrance Sand Bypass Trial

Date: Immediate

Previous Notice: 94 T & 101T are referred and cancelled

Details: Mariners are advised that the 6 month trial of a sand bypass system has commenced at Patterson River, Carrum.

The sand bypass unit is buried at the River entrance central to the north and south training walls to a depth of approximately -5.0 metres Chart Datum.

All hazards to navigation have been removed.

Mariners are advised to check updated depth information on www.parkweb.vic.gov.au.

Charts Affected: AUS 143

Further Notice: Further Notice to be issued

If you require any further information please contact Parks Victoria on 13 1963

**STUART ORD
REGIONAL MANAGER
CITY AND BAYS**

*Healthy Parks
Healthy People*

VICTORIAN NOTICES TO MARINERS



The following Notice to Mariners is published for general information.

MELBOURNE, 3 JANUARY 2005

AUSTRALIA - VICTORIA

No. 01(T)/05

VICTORIAN NOTICES TO MARINERS

NOTICES IN FORCE

Date: On the 1st January 2004

Former Notice: 01(T)/04 refers and is hereby cancelled.

Details: The following Victorian Notices to Mariners are in force. Notices can be downloaded from the Port of Melbourne Corporation website at: www.portofmelbourne.com

| No. | Region | Location | Details |
|-------------|---------------|--------------------------|--------------------------------------------------|
| 61 (T) / 00 | Western Port | Hastings | Reduced depth in channel |
| 16 (T) / 01 | Port Phillip | Port of Melbourne | Maribyrnong No.1 moorings upgraded |
| 55 (T) / 01 | Portland | Portland Harbour | Reduced depths at berths |
| 05 (T) / 02 | Port Phillip | Port of Melbourne | No. 22 Victoria Dk / Training wall construction. |
| 37 / 02 | Port Phillip | Ports of Melb. / Geel. | Amendments to Harbour Master's directions |
| 58 (T) / 02 | Port Phillip | Pinnacle Channel | Scientific research |
| 65 / 02 | Port Phillip | Port Phillip | Establishment of Marine Parks |
| 66 / 02 | Western Port | Western Port | Establishment of Marine Parks |
| 68 / 02 | Port Phillip | Port of Melbourne | Amendments to Harbour Masters directions |
| 72 / 02 | Port Phillip | Port of Melbourne | Amendments to Harbour Masters directions |
| 01 (T) / 03 | Port Phillip | Entrance to Port Phillip | Wave riders established |
| 08 (T) / 03 | Port Phillip | Entrance to Port Phillip | Wave buoys established |
| 11 / 03 | Port Phillip | Entrance to Port Phillip | Spherical buoy removed |
| 36 / 03 | Port Phillip | Ports of Melb. / Geel. | Amendments to HM directions |
| 41 (T) / 03 | Western Port | Port of Hastings | Fairway racon unreliable |
| 48 (T) / 03 | Prt. Campbell | Port Campbell | Pipe laying operations |
| 50 (T) / 03 | Bass Strait | Kilcunda | Pipe laying operations |
| 50 (T) / 03 | Bass Strait | Kilcunda | Erratum |
| 51 / 03 | Port Phillip | Ports of Melb. / Geel. | Management of port waters / HM directions |
| 52(T) / 03 | Prt. Campbell | Port Campbell | Wet storage areas |
| 62 / 03 | Port Phillip | Port of Melbourne | Amendments to HM directions |

| No. | Region | Location | Details |
|-----------|--------------|----------------------------|--------------------------------------------|
| 02/04 | Port Phillip | Port of Melbourne | Amend Harbour Masters Directions |
| 05(T)/04 | Port Phillip | Sorrento | Sorrento Channel buoy buoy |
| 36/04 | Port Phillip | Port of Geelong | Management of Port Waters - HMD |
| 54(T)/04 | Port Phillip | Port of Geelong | Declared Berth depths |
| 57/04 | Port Phillip | Hobsons Bay | Demolition of Savage Marina |
| 62/04 | Port Phillip | Port of Geelong | Port Security Port of Geelong |
| 62/Err | Port Phillip | Port of Geelong | Erratum to Port Security Geelong |
| 63(T)/04 | Westernport | Eastern entrance | Western Port / Eastern Entr. buoy |
| 64(T)/04 | Port Phillip | Port of Melbourne | Port Security Port of Melbourne |
| 66/04 | Westernport | Port of Hastings | Port Security Port of Hastings |
| 70/04 | Apollo Bay | Apollo Bay Harbour | Harbour entrance - depth reduction |
| 72(T)/04 | Gippsland | Corner Inlet & Port Albert | No.17 Beacon destroyed |
| 73(T)/04 | Port Phillip | Port of Melbourne | Declared Berth Depths |
| 75(T)/04 | Port Phillip | South Channel | Shoaling - Nicholson Knoll |
| 76/04 | Port Phillip | West Channel | West Channel closure - HMD |
| 80(T)/04 | Port Phillip | Port Phillip | Deep draught transit procedures |
| 83/04 | Port Phillip | Port Phillip | Notice to vessels Navigating off the heads |
| 91(T)/04 | Port Phillip | Corio Bay | Limeburners Pt. Boat Harbour |
| 93(T)/04 | Port Phillip | Blairgowrie | Blairgowrie Boat Harbour Maintenance |
| 96(T)/04 | Port Phillip | Dromana Bay | Construction of Rock Walls |
| 98(T)/04 | Port Phillip | Hobsons Bay | Construction of Savage Marina |
| 99(T)/04 | Port Phillip | Hobsons Bay | Demolition of Parsons Marina |
| 107(T)/04 | Gippsland | Corner Inlet & Port Albert | Barry Beach channel – reduced depth |
| 108(T)/04 | Port Phillip | Port of Melbourne | Westgate Bridge Maintenance works |
| 111/04 | Port Phillip | Werribee | Aquaculture Fisheries reserve |
| 113/04 | Port Phillip | Port of Melbourne | Fawkner Beacon – transit zone established |
| 114/04 | Port Phillip | Port of Melbourne | Channel beacons upgrade |

Victorian Notices to Mariners are issued by a number of different Authorities. This notice has been collated from the latest information held by the Port of Melbourne Corporation.

Information relating to the above notices are available at the Port of Melbourne Corporation website. Specific queries relating to Notices should be directed to the issuing authority.